

SUBJECT: NON COMPLIANCE RECALL
Safety Triangle Kits sold as aftermarket parts only from 15 August 2012 through 25 July 2014 as International® part number FLTTRIKIT3.

DEFECT DESCRIPTION

Safety triangle kits supplied by Torch Industries do not comply with Federal Motor Vehicle Safety Standard 125. The triangles fail to meet certain dimensional, red reflex color, and reflectivity requirements, and therefore may fail to warn other motorists of an impending hazard.



Figure 1. Safety Triangle Kit.

0000323661

EQUIPMENT INVOLVED

This Non-Compliance Recall only involves certain Safety Triangle Kits originally sold as aftermarket parts from 15 August 2012 through 25 July 2014 as International® part number FLTTRIKIT3.

NOTE: The enclosed laminated letter should be displayed at your service or parts counter or copied to be posted at both your service and parts counters.

PARTS INFORMATION

Request that your customer returns complete suspect safety triangle kits (P/N FLTTRIKIT3) to you for a new replacement triangle kit. Upon receipt, verify the returned kit is P/N FLTTRIKIT3 and the word FLEETRITE is molded into each triangle in the kit. Once verified, provide your customer with new triangle kit # 2204891C1.

NOTE: All returned triangle kits should be managed in accordance with instructions contained in Parts G Letter G-19-9808-A for U.S. dealers and Parts G Letter GCE-19-9808-A for Canadian dealers.

Part Number	Part Description	Quantity
2204891C1	Triangle – 3 Reflector Warning	As Necessary

NAVISTAR, INC.

NON COMPLIANCE RECALL

Safety Triangle Kits sold as aftermarket parts only from 08/15/2012 through 07/25/2014 as International[®] part number FLTTRIKIT3 do not comply with Federal Motor Vehicle Safety Standard 125. The triangles fail to meet certain dimensional, red reflex color, and reflectivity requirements, and therefore may fail to warn other motorists of an impending hazard.



0000323661

If you purchased one of these kits, return the complete kit to any International[®] or IC Bus dealer and you will receive a free replacement kit.

NAVISTAR, INC